

00862.023415.



PATENT

Cof \$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
ATSUSHI KITAOKA) Examiner: M. Kramskaya
Appl. No.: 10/763,329) Group Art Unit: 2858
Filed: January 26, 2004)
For: ELECTROSTATIC CAPACITANCE)
SENSOR TYPE MEASUREMENT)
APPARATUS)
U.S. Patent No.: 7,019,538 B2)
Issued: March 28, 2006) November 28, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULE 323

Certificate
DEC 04 2006
of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/29/2006 SZEWIEC1 00000052 7019538

01 FC:1011

100.00 02

DEC - 5 2006.

Patentee's undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Edward A. Kmett
Attorney for Patentee
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 120591v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,019,538 B2

DATED : March 28, 2006

INVENTOR(S) : Atsushi Kitaoka

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 59, "output" should read -- outputs --; and

Line 60, "firs" should read -- first --.

COLUMN 8:

Line 31, "patter)" should read -- pattern) --.

COLUMN 13:

Line 66, "anther"should read -- another --.

COLUMN 15:

Line 43, "Example" should read -- Examples --.

COLUMN 16:

Line 50, "current" should read -- currents --;

Line 51, "by 180." should read -- by 180°. --;

Line 55, "current" should read -- currents --; and

Line 56, "position." should read -- positions. --.

COLUMN 18:

Line 4, "current" should read -- currents --;

Line 5, "position." should read -- positions. --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,019,538 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
120584 (Form#30)

→ _____

2006 - 5 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,019,538 B2

DATED : March 28, 2006

INVENTOR(S) : Atsushi Kitaoka

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 59, "output" should read -- outputs --; and

Line 60, "firs" should read -- first --.

COLUMN 8:

Line 31, "patter)" should read -- pattern) --.

COLUMN 13:

Line 66, "anther"should read -- another --.

COLUMN 15:

Line 43, "Example" should read -- Examples --.

COLUMN 16:

Line 50, "current" should read -- currents --;

Line 51, "by 180." should read -- by 180°. --;

Line 55, "current" should read -- currents --; and

Line 56, "position." should read -- positions. --.

COLUMN 18:

Line 4, "current" should read -- currents --;

Line 5, "position." should read -- positions. --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,019,538 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
120584 (Form#30)

DEC - 5 2006